House 502 West 13th Street Austin Travis County Texas

HABS, TEX, 227-AUST,

PHOTOGRAPHS

HISTORICAL AND DESCRIPTIVE DATA

Historic American Buildings Survey
Heritage Conservation and Recreation Service
Department of the Interior
Washington, D. C. 20243

ECRS

nited States Department of the Interior eritage Conservation and Recreation Service lashington, D.C. 20243

COMPILER, AFFILIATION

Alison K. Hoagland, HABS

HABS TEX, 227 - AUST, 12 - NATIONAL ARCHITECTURAL AND ENGINEERING RECORD HISTORIC AMERICAN BUILDINGS SURVEY

DATE

June, 1980

ARCHITECTURAL DATA FORM

STATE	COUNTY		TOWN OR VICINITY	
Texas	Trav	ravis Austin		
HISTORIC NAME OF STRUCT	URE (INCLUDE SOUR	CE FOR NAME)		HABS NO.
House				TX-3295
SECONDARY OR COMMON NAM	ES OF STRUCTURE			
COMPLETE ADDRESS (DESCR	IBE LOCATION FOR	RURAL SITES)		
502 West 13th Street			· ·	
DATE OF CONSTRUCTION ()	NCLUDE SOURCE)	ARCHITECT(S)	INCLUDE SOURCE)	
Late 19th C.		Not known		
SIGNIFICANCE (ARCHITECT	DRAL AND HISTORIC	AL . INCLUDE OF	IGINAL USE OF STRU	CTURE)
Start for the Control of	out has around	(12)		·
A fine example of the	Italianate style	, featuring ro	und-arched windows,	rustication, and
quoining.				-
STYLE (IF APPRDPRIATE)				
<u>Italianate</u> MATERIAL OF CONSTRUCTION	M (INCLLINE STOLLET	IIDAI CVCTEMC)		
MATERIAL OF CONSTRUCTION	N (INCLUDE SINGUI	OIME 3131EH3)		
Stone				
SHAPE AND DIMENSIONS OF	STRUCTURE (SKETC	HED FLOOR PLAN	S ON SEPARATE PAGE	S ARE ACCEPTABLE)
L-Shaped Plan				
EXTERIOR FEATURES OF NO				
Full-length round-arc modillions under the		lning and rust	ication in the ston-	e; low-hipped roo
modifical ender one	wide eaves.			
INTERIOR FEATURES OF NO	TE (DESCRIBE ELOO	R PLANS IF NO	T SKETCHED)	
TRIENTON PERIONES OF NO	16 (0630)(106 1600	William, II at	JICE TOTIED)	
MAJOR ALTERATIONS AND A	DDITIONS WITH DAT	ES		
MAJOR ALTERATIONS AND A			urned balusters; no	v has lacy ironwo
	e originally had b		urned balusters; no	v has lacy ironwo
Porch on front facade	e originally had b		urned balusters; no	v has lacy ironwo:
Porch on front facade	e originally had b		urned balusters; no	v has lacy ironwo
Porch on front facade PRESENT CONDITION AND U Good: offices	e originally had b		urned balusters; no	v has lacy ironwo:
Porch on front facade PRESENT CONDITION AND U Good: offices	e originally had b		urned balusters; no	v has lacy ironwo:
Porch on front facade PRESENT CONDITION AND U Good: offices	e originally had becomes the second	oox columns, to		
Porch on front facade PRESENT CONDITION AND U Good; offices OTHER INFORMATION AS AP	e originally had becomes the second	oox columns, to		